

案例库

[退出登录 >](#)

AR1220-S ipsec vpn 隧道建立成功后数据不通 精

发布时间: 2019-07-17 | 浏览次数: 1472 | 下载次数: 0 | 文档编号: EKB1000115551

目录

[问题描述](#)[处理过程](#)[根因](#)[解决方案](#)

问题描述

拓扑如下:

192.168.14.10-----对端IPSEC加密设备-----AR1220S-----192.168.9.253。AR1220S与对端设备建立IPSEC VPN,隧道建立成功后,从192.168.9.253 ping 192.168.14.10可以通,但是从192.168.9.253 telnet 192.168.14.10 1054端口不成功。

处理过程

1. 检查两端的加密数据流以及IPSEC SA隧道信息,正常,相关信息如下:

[1]dis ipsec sa

```
=====
Interface: GigabitEthernet0/0/0
Path MTU: 1500
=====
```

```
-----
IPSec policy name: "center_vpn"
Sequence number : 1
Acl group      : 0
Acl rule       : 0
Mode           : Template
-----
```

```
Connection ID   : 1481
Encapsulation mode: Tunnel
Tunnel local    : 172.x.20.10
Tunnel remote   : 172.x.10.10
Flow source     : 192.168.9.0/255.255.255.0 0/0
Flow destination : 192.168.14.0/255.255.255.0 0/0
Qos pre-classify : Disable
Qos group       : -
```

```
[Outbound ESP SAs]
SPI: 3354115212 (0xc7ebbc8c)
Proposal: ESP-ENCRYPT-3DES-192 ESP-AUTH-MD5
SA remaining key duration (bytes/sec): 0/2949
Outpacket count : 0
```



UDP encapsulation used for NAT traversal: N

[Inbound ESP SAs]

SPI: 1560642734 (0x5d0584ae)
 Proposal: ESP-ENCRYPT-3DES-192 ESP-AUTH-MD5
 SA remaining key duration (bytes/sec): 0/2949
 Inpacket count : 0
 Inpacket decap count : 0
 Inpacket drop count : 0
 Max received sequence-number: 0
 Anti-replay window size: 32
 UDP encapsulation used for NAT traversal: N

[退出登录 >](#)

[1]dis ike sa

Conn-ID	Peer	VPN	Flag(s)	Phase
1481	172.x.10.10	0	RD	2
1478	172.x.10.10	0	RD	1

2. 在AR1220-S上display ipsec statis esp,telnet测试无报文统计,ping测试有报文统计;

3. 192.168.9.253接在Ethernet 0/0/1口上,用了一台台式机接在Ethernet 0/0/2口上,将Ethernet 0/0/2作为观察口,Ehernet 0/0/1做镜像到2上,通过报文头获取

可以看到有到1054端口的报文;

4. 同时在路由器上做1054的流量统计,抓取到了报文,如下:

Interface: Vlanif1

Traffic policy inbound: a

Rule number: 1

Current status: OK!

Item	Sum(Packets/Bytes)	Rate(pps/bps)
Matched	1/90	1/96
Passed	1/90	1/96
Dropped	0/0	0/0
Filter	0/0	0/0
CAR	0/0	0/0
Queue Matched	0/0	0/0
Enqueued	0/0	0/0
Discarded	0/0	0/0
CAR	0/0	0/0
Green packets	0/0	0/0
Yellow packets	0/0	0/0
Red packets	0/0	0/0

5. 在步骤4的同时display ipsec statistic esp 无报文,如下:

[1]dis ipsec statistics esp

Inpacket count : 0
 Inpacket auth count : 0
 Inpacket decap count : 0
 Outpacket count : 0
 Outpacket auth count : 0
 Outpacket encap count : 0
 Inpacket drop count : 0
 Outpacket drop count : 0
 BadAuthLen count : 0
 AuthFail count : 0
 InSAACLCheckFail count : 0
 PktDuplicateDrop count : 0
 PktSeqNoTooSmallDrop count: 0
 PktInSAMissDrop count : 0

以上信息表明AR1220收到了从192.168.9.253发送的telnet报文,但是没有通过IPSEC加密进行转发;192.168.9.253 ping 192.168.14.10则能够进行正常的转发。怀疑设备对于ICMP类报文进行了正常的IPSEC加密,而对于非ICMP报文走了其他的转发流程。

6. 进行一步核实配置,发现在nat outbound中已经排除了两个局域网网段的相互访问,如下:

```
acl number 3000
rule 5 deny ip source 192.168.9.0 0.0.0.255 destination 192.168.14.0 0.0.0.255
rule 10 permit ip
```

7. 查看接口上的配置,发现192.168.9.253 地址配置了NAT SERVER,以便外网访问该接口的公网地址和端口号达到访问内网地址192.168.9.253及其端口号的目的。如下:

```
interface GigabitEthernet0/0/0
description 1_Internet_R_gigabitethernet0/0/0
tcp adjust-mss 1200
ip address 172.XX.20.10 255.255.255.0
nat server protocol tcp global current-interface 8080 inside 192.168.9.253 8080
nat outbound 3000
ipsec policy center_vpn
```

查看该地址的NAT 会话,显示192.168.9.253访问对端地址时数据报文被转换到了公网,如下:



```

SrcAddr Port Vpn : 192.168.9.253 53079
DestAddr Port Vpn : 192.168.14.10 1055
NAT-Info
New SrcAddr : 172.20.10
New SrcPort :
New DestAddr :
New DestPort :

```

8. 修改nat server 为nat static再次测试telnet正常:

```
nat static protocol tcp global current-interface 8080 inside 192.168.9.253 8080
```

根因

公网出接口配置为nat server protocol tcp global current-interface 8080 inside 192.168.9.253 8080

该命令会将从192.168.9.253发出的TCP报文都做nat将报文转换掉,所以经转换后的报文无法进IPSec隧道。

将配置修改为nat static protocol tcp global current-interface 8080 inside 192.168.9.253 8080后,业务正常。

Nat static只有是源地址为192.168.9.253且TCP端口号为8080的才会做nat转换,所以修改nat static后可以正常通信。

解决方案

修改nat server为nat static protocol tcp global current-interface 8080 inside 192.168.9.253 8080后,业务正常。

上一篇: [AR1220的BGP邻居每个半个小时左右就中断一次](#)

下一篇: [AR1200 ssh登录掉线问题](#)

评论和回复

» 感谢您对我们知识库文章提供的宝贵意见

该知识库文章是否解决了您的问题: 是 否 只是浏览

*请您为该知识库文章评分: 很差 非常好

意见:

添加图片 (最多添加4张图片)

华为公司可能会与您联系, 以便帮助您尽快解决问题, 请填写您的联系信息:

联系人: 15501752377

*邮箱: 253202****@qq.com

电话: +86****377

[修改](#) [联系方式](#)

*您提交的意见内容中是否包含第三方商业秘密 否 是

↑

» 最近反馈

G*****ang 2021-12-23 11:47:34

该用户未发表意见

孟** 2020-05-16 15:03:39

z*****eng 2017-11-18 10:00:38

该用户未发表意见

何** 2016-12-05 11:45:45

非常好的案例，很清楚的解释了nat server与nat static的区别

[展开](#)

[退出登录 >](#)

S*****760 2016-10-18 14:29:56

该用户未发表意见

[展开](#)

S*****666 2016-10-18 13:46:10

该用户未发表意见

[展开](#)

杨* 2016-05-31 09:19:28

该用户未发表意见

王** 2016-05-03 15:58:06

该用户未发表意见

相关资源

[文档](#)

[软件](#)

[产品公告](#)

[工具](#)

帮助我们改进

[贡献案例](#)



[关于我们](#)



[如何购买](#)



[合作伙伴](#)



快速链接



华为亿家 App



华为亿企飞 App

